









K9129

Model # (Replaces)	P100060 Required	Replaces (Old P/N)	P100631	W2001	W3131	W2006
2853		P100073				
2899	X	P100074				
3056		P100289				
3131		P100290				
3137	X	P100547				
3149	X	P100548				
3230		P100549				
3333		P100550				
3528		P100550				
3556		P100371				
AT-CSR-040						
AT-CSR-048						

Motor Used: P100047
(Not included in K9129)







K9130

Model # (Replaces)	P100060 Required	Replaces (Old P/N)	P100631	W2002	W3131	W2006
3185	X	P100382				
3193	X	P100383				
3198	X	P100410				
3199		P100411				
3201	X	P100551				
		P100552				
		P100553				
		P100554				

Motor Used: P100338
(Not included in K9130)



K9131

Model # (Replaces)			P100632	W2001	W3131	W2006
AT-CSR-049	Ground Signal Inputs					

Motor Used: P100047
(Not included in K9131)

